


HYDROGEN SULFIDE SENSOR USER MANUAL



HYDROGEN SULFIDE SENSOR MANUAL

Copyright © 2012 · Unisense A/S Version October 2012

HYDROGEN SULFIDE SENSOR MANUAL

UNISENSE A/S

TABLE OF CONTENTS

WARRANTY AND LIABILITY	6
CONGRATULATIONS WITH YOUR NEW PRODUCT!	7 7
OVERVIEW	9
GETTING STARTED	11
POLARIZE PICOAMMETER	11
Connecting the microsensor	11
Pre-polarization	11
Calibration	12
Calibration theory	12
Calibration in the laboratory	14
Calibration in the field	16
Re-calibration	17
MEASUREMENTS	18
Mounting the sensors	18
ELECTRICAL NOISE	18
pH influence	18
Interference	19
ADVANCED USE	20
STORAGE AND MAINTENANCE	21
CLEANING THE SENSOR	21
REFERENCES	22
TROUBLE SHOOTING	23

WARRANTY AND LIABILITY

Notice to Purchaser

This product is for research use only. Not for use in human diagnostic or therapeutic procedures.

WARNING

Microsensors have very pointed tips and must be handled with care to avoid personal injury and only by trained personnel.

Unisense A/S recommends users to attend instruction courses to ensure proper use of the products.

WARRANTY AND LIABILITY

The hydrogen sulfide microsensor is covered by a 90 days limited warranty. Microsensors are a consumable. Unisense will only replace dysfunctional sensors if they have been tested according with the instructions in the manual within 14 days of receipt of the sensor(s). The warranty does not include repair or replacement necessitated by accident, neglect, misuse, unauthorized repair, or modification of the product. In no event will Unisense A/S be liable for any direct, indirect, consequential or incidental damages, including lost profits, or for any claim by any third party, arising out of the use, the results of use, or the inability to use this product.

Unisense mechanical and electronic laboratory instruments must only be used under normal laboratory conditions in a dry and clean environment. Unisense assumes no liability for damages on laboratory instruments due to unintended field use or exposure to dust, humidity or corrosive environments.

REPAIR OR ADJUSTMENT

Sensors and electrodes cannot be repaired. Equipment that is not covered by the warranty will, if possible, be repaired by Unisense A/S with appropriate charges paid by the customer. In case of return of equipment please contact us for return authorization.

For further information please see the document General Terms of Sale and Delivery of Unisense A/S as well as the manuals for the respective products.

CONGRATULATIONS WITH YOUR NEW PRODUCT!

SUPPORT, ORDERING, AND CONTACT INFORMATION

The Unisense hydrogen sulfide microsensor is a miniaturized Clark-type hydrogen sulfide sensor designed for reliable and fast measurements in a large number of research applications.

If you wish to order additional products or if you encounter any problems and need scientific/technical assistance, please do not hesitate to contact our sales and support team. We will respond to your inquiry within one working day.

E-mail: sales@unisense.com

Unisense A/S Tueager 1 DK-8200 Aarhus N, Denmark Tel: +45 8944 9500

Fax: +45 8944 9549

Further documentation and support is available at our website www.unisense.com.

REPLACEMENT OF SENSORS

Unisense will replace sensors that have been damaged during shipment provided that:

- The sensors were tested immediately upon receipt in accordance with the delivery note and the manual
- The seal is still intact.
- The sensors are returned to Unisense for inspection within two weeks.
- The sensors are correctly packed for return to Unisense, in accordance with the note included in the sensor box.

RECOMMENDED AMPLIFIERS

One-channel amplifier: Microsensor Monometer Multi-channel amplifiers: Microsensor Multimeter

OVERVIEW

This manual covers all the Unisense hydrogen sulfide sensors.

The Unisense H₂S microsensor is a miniaturized amperometric sensor with a guard electrode. The microsensor is designed for research applications within physiology, biotechnology, environmental sciences, and related areas.

With its minute tip size, excellent response time, and minimal stirring sensitivity, the Unisense H₂S sensor makes it possible to make reliable and fast measurements at high spatial resolution.


The Unisense H₂S microsensor is a miniaturized amperometric sensor with an internal reference, a sensing and a guard anode. The sensor is connected to a high-sensitivity picoammeter and the anodes are polarized against the internal reference. Driven by the external partial pressure, H₂S from the environment will penetrate through the sensor tip membrane into the alkaline electrolyte, where the HS⁻ ions formed are oxidized immediately by ferricyanide, producing sulfur and ferrocyanide. The sensor signal is generated by re-oxidation of ferrocyanide at the anode in the tip of the sensor (Jeroschewski et al. 1996). The Unisense picoampere amplifier converts the resulting reduction current to a voltage signal. Also the internal guard electrode is polarized to scavenge H₂S and helps keeping a constant ratio of ferri- to ferro cyanide in the electrolyte, thus minimizing zero-current.

For calculation of total sulfide concentrations, it is necessary to know the pH. When measuring H₂S in pH gradients, pH should be measured along the same profile with a pH microsensor (e.g. Unisense PH10/PH25).

The LEMO connector contains connections for both reference, guard, and sensing cathode.

IMPORTANT

Unisense sensors are neither intended nor approved for use of humans



The electrolyte in the H₂S microsensor is photo-degraded by high light intensities – especially UV and blue light. This is seen as a higher signal in light as compared to the signal in darkness for the same amount of H₂S. The sensors are painted black to protect them against light. Light may however, still enter the sensor through the tip, which it is not possible to paint.

GETTING STARTED

UNPACKING A NEW SENSOR

When receiving a new microsensor remove the shock-absorbing grey plastic net. Please do not remove the seal and protective tube before the following steps are successfully completed.

NOTE: if you have a H₂S-MR electrode, calibrate in the protective tube and then carefully move the sensor from this tube into the provided blue guide.

POLARIZE PICOAMMETER

The signal from the $\rm H_2S$ sensor is generated in pA. Therefore the $\rm H_2S$ sensor must be connected to a Unisense picoampere amplifier during measurements.

H2S sensors should be polarised with +85mV (on legacy PA2000 meters value is set at +0.08V). On the Microsensor Multimeter and Microsensor Monometer, sulfide sensors with lemo-connectors are automatically recognized and polarization automatically set. If you are using another amplifier or sensor connection type, please check the polarization voltage before connecting a sensor, since incorrect polarization may destroy the sensor.

For details on how to set the polarization, consult the user manual of the amplifier that you are using.

CONNECTING THE MICROSENSOR

Connect the LEMO connector to the input terminal. The LEMO connector contains connections for both reference, guard and sensing anode.

PRE-POLARIZATION

When the sensor is not in use, hydrogen sulfide will build up inside the electrolyte. This must be removed by the sensing anode and the guard anode before stable operation of the sensor is possible.

WARNING

Do not remove the seal and protective plastic tube before the following steps (1-4) and calibration are succesfully completed.

IMPORTANT

If you have a H₂S-MR electrode, calibrate in the protective tube and then carefully move the sensor from this tube into the provided blue quide.

PREPOLARIZATION

If the sensor is new or has not been operated for several days, then it must be polarized for at least 2 hours before it can be calibrated and used. After shorter periods without polarization, the sensor should be polarized until it has exhibited a stable sianal for 10 minutes.

Therefore, a period of polarization is necessary before you can use the sensor. This is called the pre-polarization period.

If the sensor is new or has not been operated for several days, it must be pre-polarized for at least 2 hours before it can be calibrated and used. After shorter periods without polarization, the sensor should be pre-polarized until it has shown a stable signal for at least ten minutes.

When pre-polarization is initiated, the signal will be very high and then drop rapidly over the first few minutes. After that, the signal will drop slowly for up to two hours (for needle- and some custom made sensors slightly longer). It takes normally between 10 minutes and an hour before a sensor is stable.

The sensor signal depends on the specific sensor (see the delivery note which came with the sensor). If the signal does not stabilize or is too high or too low, refer to the 'Troubleshooting' section.

CALIBRATION

CALIBRATION THEORY

The sensor detects the partial pressure of H₂S gas, which is only one component of the total sulfide equilibrium system. If the total sulfide concentration,

[S-2tot], is defined as:

$$S_{tot}^{-2} = [H_2S] + [HS^-] + [S^{2-}]$$

the H₂S concentration will be defined as

$$[H_2S] = [S_{tot}^{-2}] / \left(1 + \frac{K_1}{[H_30^+]} + \frac{K_1K_2}{[H_30^+]^2}\right)$$

$$[H_3O^+] = [H^+] = 10^{pH}$$

which can be simplified to

$$[H_2S] = [S_{tot}^{-2}] / \left(1 + \frac{K_1}{[H_3O^+]}\right)$$

for pH<9 (Jeroschewski et al. 1996). Thus it is necessary to know the pH (i.e. to know $[H_3O^+]$) of the sample/calibration solution to calculate $[S_{tot}^{-2}]$ (see Figure 1).

IMPORTANT

Calibration must be performed after pre-polarization when the sensor signal has stabilized.
Always use a calibration solution with the same temperature and salinity as the sample solution.

$$pH = -log[H^+]$$

In solutions with a pH below 4 the equation can be simplified to:

$$[H_2S] \approx [S_{tot}^{-2}]$$

$$K_{_{1}} = 10^{-pK1}$$

 pK_1 is dependent on temperature and salinity. The literature gives slightly different equations for calculating pK_1 in water as a function of temperature (T) and salinity (S).

The following equation is derived by Millero et al. 1988:

$$pK_{_{1}} = -98.08 + 5765.4/T + 15.04555 * LN(T) + (-0.157 * (S^{0.5})) + 0.0135 * S$$

(Temperature in Kelvin)




Figure 1. The species distribution of H2S, HS and S2- as a function of pH.

As H₂S sensors are sensitive to temperature, it is necessary to perform calibration and measurements at the same temperature.

Please note that, in contrast to oxygen, the relationship between salinity, temperature and solubility is not well known and therefore not tabled for sulfide gas

CALIBRATION IN THE LABORATORY

Calibration must be performed after the sensor signal has stabilized during pre-polarization. The $\rm H_2S$ microsensor responds linearly over a certain range (e.g. 0-300 μM), above which the slope of the response curve decreases, but the response and resolution above the linear range may be sufficiently good for reliable measurements. We suggest that you establish the linear range by making a coarse calibration in the entire concentration range of interest. If measurements of concentrations above the linear range are needed, a calibration with sufficient resolution has to be made in the non-linear range, whilst a 3-point calibration is sufficient in the linear range.

Please read the entire procedure below before the calibration is commenced. It is best to first prepare the stock solution so it is ready. Then prepare the buffer and perform the calibration quickly thereafter in order to avoid reintroduction of oxygen.

NOTE: for field calibrations, an alternative method is recommended - this will enable you to prepare reagents to bring into the field for easy calibration.

Laboratory calibration

1. Prepare a stock solution

A stock solution of S^{2-} (\approx 0,01M total sulphide) is prepared anaerobically by dissolving 0,24 g $\text{Na}_2\text{S}*9\,\text{H}_2\text{O}$ in 100mL of N_2 -flushed water in a closed container. The final concentration of the stock solution should be determined by standard analysis (e.g. Cline 1969 or Budd & Bewick 1952). Keep the stock solution out of contact with oxygen.

2. Prepare the calibration buffer

Any standard pH buffer, with a pH value less than 4, can be used. Remove oxygen from a volume of the buffer. This can be done in

IMPORTANT

It is important
to perform
calibration and
subsequent
measurements in
solution with the
same temperature
and salinity.

FIELD CALIBRATION

For field calibrations, please see alternative calibration procedure below.

WARNING

Vigorous bubbling
water with any
gas may cause
the water to cool
considerably.
Monitor the
temperature to find
a suitable bubbling
rate, which does
not cool the water
significantly.

two ways: WARNING

a. By vigorously bubbling with an oxygen-free inert gas (e.g. N₂) for at least 5 minutes. NOTE: Vigorously bubbling buffer with any gas may cause the water to cool considerably. Monitor the temperature to find a suitable bubbling rate, which does not cool the buffer significantly.

b. By adding a suitable reductant (e.g. Ti(III)CI; MERCK supplies this in a 10% HCI solution) to the oxygen free buffer to a final concentration of 50 mM. Add a few glass beads (2-3 mm in diameter) to facilitate mixing. The transfer is preferably performed with a pipette to minimize mixing with oxygen, and a maximum of 10% of the vial volume should be left as headspace. Close the container with a gas tight lid and shake vigorously.

3. Obtain zero reading

The signal at zero $\rm H_2S$ can be obtained by immersing the sensor tip into one of the vials with calibration buffer. Note the signal, which is the calibration value for zero $\rm H_2S$ partial pressure (S0). This signal should be 0-30 pA (otherwise see "Troubleshooting").

4. Obtain sulfide standard readings

Calibration points within the expected range of measurement are prepared by injecting suitable amounts of the S^{2-} stock solution anaerobically into the calibration buffer with a micro-syringe (the stock solution should be diluted at least 10 times). Mix the solutions. If you have not added reductant, oxygen that dissolve in the calibration solution will oxidize the sulfide, so the stock solution should be added immediately after the oxygen removal (e.g. N_2 bubbling) and the calibration should be done immediately after adding the stock solution.

It may be difficult to use a standard analysis for sulfide in your calibration solution (e.g. Cline 1969) when a reductant has been added. For each calibration solution, measure the calibration values by removing the rubber stopper and immerse the microsensor tip into the solution. Read the signal and plot it against the concentration.

The most precise calibration curve is obtained by fixing the calibration solutions with Zn-acetate and subsequently determining the total sulfide concentration using the Cline method (Cline 1969). This may, due to the nature of the method, be difficult if a reductant has been added previously.

CALIBRATION IN THE FIELD

For an easy and portable field calibration, prepare the following reagents in the lab. Bring the reagents and a 1 ml syringe+needle to the field.

Reagent 1:

- 1mM Na₂S
- 1mM NaOH

Prepare the solution in a membrane flask with gas-tight lid. After mixing, flush the solution with nitrogen gas to remove all oxygen and quickly place the lid on the flask.

During storage, practically all sulfide in Reagent 1 will be in alkaline form and since it is stored in an gas-tight vial, it cannot evaporate to any significant degree.

Reagent 2:

- 0.1 M HCI
- 50mM TiCl

As the TICl is a strong reducing agent, all oxygen will be reduced in the mixture, but it is still recommended that you avoid introducing too much oxygen during mixing.

Fill reagent 2 into a 10 ml glass vial with gas-tight membrane lid. Avoid head space. **Prepare as many vials as the number of calibrations you expect to make**. Bring reagent 1, the vials with reagent 2 and 1 ml syringe+needle with you to the field.

Calibration in the field.

Perform the zero point determination in clean water (without H₂S) at field site temperature.

Prepare a 100 μ M calibration standard. Perform the calibration quickly after mixing as the durability of the mix is short.

- Loosen the lid of a reagent 2 vial and remove carefully 1 ml with a syringe+needle through the lid. Throw this away.
- 2. Take 1ml of reagent 1 and add it to the reagent 2 vial.
- 3. Tighten the lid and mix.
- 4. Remove the lid and place the sensor tip carefully in the vial and perform the 100 μ M calibration.

For making higher or lower concentrated H₂S calibration solutions, make reagent 1 more or less concentrated with Na₂S.

RE-CALIBRATION

Check the calibration at appropriate time intervals and repeat it, if the sensor exhibits significant drift. When the sensor is new, you may need to calibrate it every two hours. An older extensively used sensor may require calibration only every 24 hours or less. To minimize the need for calibration, keep the sensor polarized between measurements if possible (unless the time between measurements exceeds several days). If the signal does not stabilize or remains too high or too low, refer to the "Troubleshooting" section in this manual.

The response of the H₂S microsensor does change with time, and a decrease in signal of up to 50% pr. month is to be expected. This does not affect the quality of the measurements as long as the sensor is regularly calibrated.

MFASURFMENTS

MOUNTING THE SENSORS

Due to the small size of the microsensor tip and the steepness of $\rm H_2S$ gradients in many environments, even a few microns' displacement of the sensor tip may change its immediate $\rm H_2S$ environment. The sensor tip is quite flexible and can bend around physical obstacles. But coarse lateral movements of the sensor when its tip is in contact with a solid substrate may easily cause the tip to break.

Therefore measurements should be performed only in a stabilized set-up fixed on a sturdy table free of moving or vibrating devices. We recommend the Unisense lab stand LS18 and the Unisense micromanipulator MM-33 (MM33-2 or MMS) for this purpose.

ELECTRICAL NOISE

The signal of the microsensor is very small (10^{-10} to 10^{-13} ampere). Although both the Unisense picoammeters and the Unisense H_2S microsensors are very resistant to electrical noise from the environment, electrical fields may interfere with the sensor signal. Therefore we recommend that unnecessary electrical/mechanical equipment is switched off and by the sensor or wires are not touched during measurements and signal recording. On suspicion of sensor damage, repeat calibration and consult "Troubleshooting".

PH INFLUENCE

As mentioned above, the H_2S concentration is a function of pH. If measurements of H_2S are performed in points along a pH gradient, pH should be measured in the same points with a pH microsensor (e.g. Unisense PH10/PH25/PH100) to allow the determination of the total sulfide concentration. Use the equations in the calibration section in order to calculate [S^{-2} tot].

Ferro cyanide reacts in light, especially blue (short-wave) light.

WARNING

Measurements in a light gradient should be avoided, and interpretation of measurements in a light gradient should be made with the light interference in mind.

Thus light increases the signal of the H₂S sensor by increasing the zero current. This means that when measuring through a light gradient (e.g. when measuring into an illuminated biofilm) the signal will decrease slightly, when entering the biofilm. In many systems the light will be almost completely attenuated within the first few hundred microns.

INTERFERENCE

There is a slight linear interference from hydrogen on the sulfide sensor. At the same concentration, hydrogen will be responsible for 1.15% of the signal. This means that 1 μ M H₂ = 0.015 μ M H₂S.

Light gives a false H₂S sensor signal. The sensor has been painted black to reduce this phenomen, however light may still enter the sensor through the tip, which is not possible to paint.

WARNING

Always introduce and retract the microsensor axially using a micromanipulator and a stable stand when measuring in solid or semisolid substrate like sediment, tissue, biofilms, microbial mats etc.



Micromanipulator

ADVANCED USE

Unisense can construct H₂S sensors for customer requested applications at additional costs. The most frequently construction options are described at our web page.

The options include for instance customer specified dimensions, cable length etc. If your specifications for a special H₂S sensor are not described at our web page please contact sales@unisense.com for further options.

STORAGE AND MAINTENANCE

Store the H₂S microsensor unpolarized in the protective glass tube used for shipping. Due to the light sensitivity of the electrolyte H2S, microsensors should be applied and stored at low to moderate levels of light. The sensor can be stored with the tip exposed to water or air. The room in which the H₂S microsensor is stored should be dry and not too hot (about 5-35°C).

LIGHT SENSITIVITY

Due to the light sensitivity of the electrolyte H₂S, microsensors should be applied and stored at low to moderate levels of light.

CLEANING THE SENSOR

Standard procedure: Rinse with 96% ethanol, rinse with 0.01 M HCl and rinse with water.

Alternatively rinse with: 0.1M NaOH Isopropanol Detergent

REFERENCES

- Borum, J. et al. (2005) The potential role of plant oxygen and sulphide dynamics in die-off events of the tropical seagrass, *Thalassia testudinum*. Journal of Ecology 93: 148-158
- Budd, M.S. & Bewick, H.A. 1952: Photometric determination of hydrogen Sulfide and reducible sulfur in alkalines. Analytical Chemistry 24: 1536-1540.
- Cline J. D. (1969): Limnol. and Oceanogr. 14: 454-458.
- Jeroschewski P, Steuckart C & Kühl M (1996)
 Anal. Chem. 68:4351-4357
- Kühl M, Steukart C, Eickert G & Jeroschewski (1998): Aquat. Microb. Ecol. 15:201 209

TROUBLE SHOOTING

Problem A high and drifting signal

Possible cause 1 Gas bubbles are present inside the sensor tip due to a short circuit

or electrical shock.

Solution Degas water by boiling and **subsequent cooling** or by 10 minutes

of vacuum treatment. Immerse the sensor tip for 20 min in the degassed water. Repeated or prolonged treatment may be

necessary.

Possible cause 2 The sensor tip is broken.

Solution Replace the H₂S microsensor.

Problem A slow response.

Possible cause Insoluble compounds deposited on the sensor tip.

Solution Rinse with 96% ethanol, rinse with 0.01 M HCl and rinse with

water.

Problem Measurements in two environments with equal H₂S concen

trations exhibit different signals.

Possible cause The light intensity differs between the two environments, causing

different light interference.

Solution Try to keep constant light conditions and interpret data with the

light interference in mind.

Problem Signal unstable fluctuatung if the set-up is touched or equipment

is introduced in the medium

Possible cause Electrical disturbance through the tip membrane

Solution Ground the set-up by connecting the reference plug on the

picoammeter (blue plug) with the medium you are measuring in. Use the provided blue grounding wire. Leave the other end with approximately 1 cm un-insulated wire (If you are measuring in e.g.

a sediment, just put the open wire end in the water column).

If you encounter other problems and need scientific/technical assistance, please contact sales@unisense.com for online support (we will answer you within one workday)



UNISENSE, DENMARK www.unisense.com · info@unisense.com